



FM2M ToolBox Color LCD radios

Manufacturer	Model	0.9x	1.0x	Remarks
Radiomaster	TX16S	v	v	
Jumper	T16	v	v	
	T15	x	v	
	T18	v	v	
FlySky	NV14	x	v	
	EL18	x	v	
FrSky	X10	v	v	
	X12S	v	v	

FM2M ToolBox B&W LCD radios



Manufacturer	Model	0.9x	1.0x	Remarks
Radiomaster	T8	v	v	
	TX12	v	v	Low memory radio
	TX12 mk2	v	v	Low memory radio
	Zorro	v	v	
	Pocket	v	v	
	Boxer	v	v	
Jumper	T12	v	v	
	T12 max	v	v	
	T20	x	v	
	T20 v2	x	v	
	T-Lite	v	v	
	T-Pro	v	v	
	T-Pro S	v	v	
	T-Pro v2	v	v	
iFlight	commando8	x	v	
BetaFPV	LiteRadio 3 Pro	x	v	Low memory radio
FrSky	QX7	v	v	Low memory radio
	X9D	v	v	Low memory radio
	X9D 2019	v	v	Low memory radio
	X9 Lite	v	v	Low memory radio
	X9 Lite S	v	v	Low memory radio
	X-Lite	v	v	Low memory radio
	X-Lite S	v	v	Low memory radio
	X-Lite Pro	v	v	Low memory radio

On low memory radios Toolbox 1,00 may crash due to not sufficient memory for all fractures.